


A 3H:1V Slope



B. 10H:1V Slope

**Figure 4-1**

Illustration of Cap Design Thickness

Holly Street Landfill/Whatcom Creek Estuary Restoration  
City of Bellingham Office of Neighborhoods & Community Development